



For immediate release

Contact :

David Molins

For Otis

+33 (0) 6 15 65 69 02

david.molins@utc.com

STOCKHOLM, JULY 14, 2018 — On July, 9th 2018, an Otis escalator installed at the Stockholm City railway station (Stockholm, Sweden) reversed direction. There have been no reports of serious injuries. The incident is currently under investigation and Otis is fully cooperating in the investigation. There is nothing more important to Otis than the safety of the people who count on our products and services every day.

Our local team is on site, and Otis has also dispatched global equipment experts to support the investigation.

Some escalators at the Citybanan railway stations are temporarily unavailable as we assist in inspecting all the units there. We deeply regret the inconvenience, however safety is always our highest priority. We are working to resolve the situation as soon as possible.

####



Pressmeddelande

För mer information:

David Molins

För Otis

+33 (0) 6 15 65 69 02

david.molins@utc.com

STOCKHOLM, JULI 14, 2018 — Den 9 juli 2018 började en av Otis rulltrappor på stationen Stockholms City att gå baklänges. Några allvarliga skador till följd av detta har inte rapporterats. Händelsen är för närvarande under utredning och Otis samarbetar fullt ut i denna utredning. Det finns inget viktigare för Otis än säkerheten för de människor som dagligen använder och förlitar sig på våra produkter och tjänster.

Vårt lokala team finns på plats och Otis har även kallat in globala utrustningsexperter för att ytterligare stödja utredningen.

Medan samtliga enheter inspekteras är vissa rulltrappor på Citybanans stationer för tillfället tagna ur bruk. Vi beklagar djupt det besvär som detta orsakar, men säkerhet är alltid vår högsta prioritet. Vi arbetar för att lösa situationen så snart som möjligt.

####